Yext Rule Service Code Service Code Next Rule Service Code Next R

TITLE 22 EXAMINING BOARDS

PART 23 TEXAS REAL ESTATE COMMISSION

CHAPTER 535 GENERAL PROVISIONS

SUBCHAPTER R REAL ESTATE INSPECTORS

RULE §535.231 Standards of Practice: Minimum Inspection Requirements

for Plumbing Systems

- (a) Plumbing systems. The inspector shall:
- (1) report:
- (A) static water pressure;
- (B) location of water meter; and
- (C) location of main water supply valve; and
- (2) report as Deficient:
- (A) the presence of active leaks;
- (B) the lack of fixture shut-off valves;
- (C) the lack of dielectric unions, when applicable;
- (D) the lack of back-flow devices, anti-siphon devices, or air gaps at the flow end of fixtures;
- (E) water pressure below 40 psi or above 80 psi static;
- (F) the lack of a pressure reducing valve when the water pressure exceeds 80 PSI;
- (G) the lack of an expansion tank at the water heater(s) when a pressure reducing valve is in place at the water supply line/system; and
 - (H) deficiencies in:
 - (i) water supply pipes and waste pipes;
 - (ii) the installation and termination of the vent system;
 - (iii) the operation of fixtures and faucets not connected to an appliance;
 - (iv) water supply, as determined by viewing functional flow in two fixtures operated simultaneously;
 - (v) functional drainage at fixtures;

(B) leaking or corroded fittings or tank(s);

(A) inoperative unit(s);

(A) gas leaks;

(4) in electric units, report as Deficient deficiencies in:

(A) operation of heating elements; and

(B) condition of conductors; and

(5) in gas units, report as Deficient:

- (B) lack of burner shield(s);
- (C) flame impingement, uplifting flame, improper flame color, or excessive scale build-up;
- (D) the lack of a gas shut-off valve; and
- (E) deficiencies in:
- (i) combustion and dilution air;
- (ii) gas shut-off valve(s) and location(s);
- (iii) gas connector materials and connections; and
- (iv) vent pipe, draft hood, draft, proximity to combustibles, and vent termination point and clearances.
- (d) Specific limitations for water heaters. The inspector is not required to:
- (1) verify the effectiveness of the temperature and pressure relief valve, discharge piping, or pan drain pipes;
- (2) operate the temperature and pressure relief valve if the operation of the valve may, in the inspector's reasonable judgment, cause damage to persons or property; or
- (3) determine the efficiency or adequacy of the unit.
- (e) Hydro-massage therapy equipment. The inspector shall report as Deficient:
- (1) inoperative unit(s) and controls;
- (2) the presence of active leaks;
- (3) inaccessible pump(s) or motor(s);
- (4) the lack or failure of required ground-fault circuit interrupter protection; and
- (5) deficiencies in the ports, valves, grates, and covers.
- (f) Specific limitation for hydro-massage therapy equipment. The inspector is not required to determine the adequacy of self-draining features of circulation systems.

Source Note: The provisions of this §535.231 adopted to be effective February 1, 2009, 33 TexReg 9242

Next Page Previous Page

List of Titles Back to List

HOME I TEXAS REGISTER I TEXAS ADMINISTRATIVE CODE I OPEN MEETINGS I HELP I